

CARBON MONO-OXIDE METER



• CO-180

Included Accessories

- Battery
- Carrying Case
- Instruction Manual



The Carbon Monoxide Meter detects the presence of carbon monoxide (CO) and measures concentrations between 1-1000 parts per million (PPM).

The Meter indicates the presence of carbon monoxide in two ways:

- By a reading on the LCD in PPM.
- By a beeper tone.

Features	
Backlit LCD Display	
Auto Zero	
High Accuracy / Quick Response	
Pocket Size, Easy to use	
Fast Sampling	
Max Hold / Data Hold	
Auto Power Off	
Beeper Sound above 200PPM	

SPECIFICATIONS (Check the CEM web for detailed specifications)

Operating Temperature	0°C to + 50°C
Storage Temperature	-30°C to + 60°C
Operating Humidity	0-99% Relative humidity (non-condensing)
Measurement Range	0 to 1000PPM
Measurement Resolution	1PPM
Accuracy	±5% or ± 10 PPM
Warm up Period	<2 seconds
Battery	9V, NEDA 1604A or IEC 6LR61, or equivalent.
Sensor Type	Stabilized electrochemical Gas-specific (CO)